

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

## OLENE S. WALKER Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representative	es Present During the Inspection:	
Company	Alden Gustefsen Permit Coordinator	
OGM	Joe Helfrich Environmental Scientist III	

# **Inspection Report**

Darmit Number	C0070011			
Permit Number:	C0070011			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, November 24, 2004			
Start Date/Time:	11/24/2004 9:30:00 AM			
End Date/Time:	11/24/2004 2:00:00 PM			
Last Inspection:	Thursday, September 23, 2004			

Inspector: Joe Helfrich, Environmental Scientist III

Weather: Sunny 50

InspectionID Report Number: 466

Accepted by: whedberg

12/6/2004

Permitee: HIAWATHA COAL CO INC
Operator: HIAWATHA COAL CO INC
Site: HIAWATHA MINE COMPLEX

Address: PO BOX 1202, HUNTINGTON UT 84528

County: CARBON

Phase II
Phase III

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

12,177.00 Total Permitted

**Current Acreages** 

Mineral Ownership	Types of Operations			
<b>✓</b> Federal	✓ Underground			
☐ State	Surface			
☐ County	☐ Loadout			
<b>✓</b> Fee	Processing			
Other	Reprocessing			

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the Hiawatha complex. Mining activities consist of occasional slurry fines loaded on to rail cars. There are no pending permit conditions or amendments and no compliance issues.

Inspector's Signature

oe Helfrich, Environmental Scientist III
Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov



Date \_

Tuesday, November 30, 2004

**Inspection Continuation Sheet** 

Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Wednesday, November 24, 2004

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
     b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	<b>✓</b>		$\checkmark$	
2.	Signs and Markers	<b>V</b>		<b>V</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<b>✓</b>		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	o Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

**Inspection Continuation Sheet** 

Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Wednesday, November 24, 2004

Page 3 of 3

## 1. Permits, Change, Transfer, Renewal, Sale

There are no current plans to re-open the mine.

#### 2. Signs and Markers

Signs containing the required information were posted at access points to the property.

## 4.a Hydrologic Balance: Diversions

There are two culverts near the RR tracks by the #1 slurry pond. One is maintained by the RR and the other by Hiawatha Coal Co. At the time of this inspection both culverts were clean except for the inlet to the RR culvert. Alden suggested cleaning the inlet in order to maintain the integrity of their culvert. Photos were taken to monitor sediment loading in the ditches and culverts.